Appendix 1 – Pluto LNG Project Construction Commencement Photo Plates.

Construction co Statement 757. construction.	ommenced on Photos have	15 October 20 been provide	007. Proposal ed of site cor	has been impl estruction activi	emented as requities to documen	uired by Ministerial t the beginning of

Pluto LNG Project Construction Annual Compliance Report



Plate 1: Site A Construction works, 19 October 2008. LNG Storage Tank 1, roof was lifted on 25 September 2008.



Plate 2: Site B Earthworks and pad preparation in preparation for train installation, 19 October 2008.



Plate 3: Construction equipment and vehicles, August 2008.



Plate 4: First preassembled pipe rack installed on Site A, November 2008.




Plate 5: Construction of LNG Storage Tank, August 2008. Construction works still being undertaken on the roof prior to lift.



Plate 6: Condensate Tank outer shell construction, October 2008.



Plate 7: Pluto LNG Project construction site security gate (checkpoint to verify vehicle inspection for weed and seeds), July 2007.



Plate 8: Earthworks on Site B, July 2007.



Plate 9: Water truck used for dust suppression, Site A, July 2008.



Plate 10: Site A construction, Jetty piling commenced after the completion of the Phase 1 dredging program, June 2008.